



# EASA Safety Information Bulletin

Transportstyrelsens utskick av SIB

*Christian Lofur  
Flyginspektör*

*Sjö- och luftfartsavdelningen, Sektionen för helikopter, allmänflyg och fritidsbåtar*

# Ny service till operatörerna helikopter

- Första utskicket från sektionen för helikopter, allmänflyg och fritidsbåtar 2016-12-02
- Åtgärd efter anmärkning från EASA
- Inte säkert Transportstyrelsen skickar ut alla SIB som är relevanta för alla operatörer
- Ansvaret ligger hos operatörerna

- ad.easa.europa.eu

AD Biweekly reports

Biweekly	From	To	CSV	HTML	PDF
01	2015-12-21	2016-01-03	262 b	2 kb	26 kb
02	2016-01-04	2016-01-17	3 kb	10 kb	36 kb
03	2016-01-18	2016-01-31	2 kb	8 kb	32 kb
04	2016-02-01	2016-02-14	2 kb	6 kb	31 kb
05	2016-02-15	2016-02-28	2 kb	8 kb	33 kb
06	2016-02-29	2016-03-13	4 kb	11 kb	38 kb
07	2016-03-14	2016-03-27	4 kb	11 kb	40 kb
08	2016-03-28	2016-04-10	2 kb	7 kb	33 kb
09	2016-04-11	2016-04-24	4 kb	11 kb	38 kb
10	2016-04-25	2016-05-08	3 kb	10 kb	35 kb
11	2016-05-09	2016-05-22	2 kb	7 kb	32 kb
12	2016-05-23	2016-06-05	2 kb	8 kb	34 kb
13	2016-06-06	2016-06-19	4 kb	11 kb	38 kb
14	2016-06-20	2016-07-03	3 kb	9 kb	34 kb
15	2016-07-04	2016-07-17	3 kb	9 kb	34 kb
16	2016-07-18	2016-07-31	4 kb	11 kb	42 kb
17	2016-08-01	2016-08-14	2 kb	7 kb	32 kb
18	2016-08-15	2016-08-28	1 kb	5 kb	30 kb
19	2016-08-29	2016-09-11	2 kb	7 kb	32 kb
20	2016-09-12	2016-09-25	3 kb	8 kb	33 kb
21	2016-09-26	2016-10-09	3 kb	9 kb	35 kb
22	2016-10-10	2016-10-23	3 kb	9 kb	34 kb
23	2016-10-24	2016-11-06	3 kb	9 kb	35 kb
24	2016-11-07	2016-11-20	2 kb	6 kb	31 kb

easa\_biweekly\_23-2016.pdf - Adobe Reader

File Edit View Window Help

57,1%

1 / 2

Fill & Sign Comment

Biweekly 23-2016, report of Safety Information Publications between 24/10/2016 - 06/11/2016

esasa.europa.eu

Publ. number	Issue Date	TC Holder	Type	Subject
2016-0220	2016-11-04	AIRBUS HELICOPTERS	A3 350 / EC 130	Rotor Flight Controls - Dual Hydraulic System - Modification
2016-0221	2016-11-04	ENSTROM HELICOPTER CORPORATION	280, 480, F-28	Main Rotor - Main Rotor Spindle - Inspection Centre/Auxiliary Tank Fuel Boost Pumps Installation - Modifications / P-2 Fuel System Module Assembly - Replacement / AFM - placard and Maintenance Program Changes
US-2016-16-16	2016-11-03	BOEING	737	High Pressure Turbine Stage 2 Nozzles - Inspection / Replacement
US-2016-22-11	2016-11-03	ENGINE ALLIANCE LLC	GP7200	Landing Gear - Nise Landing Gear Hydraulic Control Unit - Replacement
2016-0219	2016-11-03	AIRBUS	A340	Fuselage - Cracking on the Forward Face of the Rear Pressure Bulkhead/ Web
CF-2011-30R1	2016-11-03	BOMBARDIER	CL-600 (Regional Jet)	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Amendment
2016-0217	2016-11-02	AIRBUS	A310	Time Limits / Maintenance Checks - Landing Gear Parts Life Limitations - Implementation
BR-2016-07-02	2016-11-02	EMBRAER	EMB-120	Flight Controls - Gust Lock Lever - Replacement
BR-2016-07-01	2016-11-02	EMBRAER	EMB-135, EMB-145	Engine Fuel & Control - Fuel Nozzles - Initial and Repetitive Inspections / Replacement
US-2016-22-05	2016-11-02	PRATT & WHITNEY	PW4100	Engine Fuel & Control - Woodward Fuel Control Unit - Inspection / Update of Airplane Operating Procedures
US-2016-21-07	2016-11-02	HONEYWELL INTERNATIONAL INC.	TPE331	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Amendment
2016-0218	2016-11-02	AIRBUS	A300-600	Fuselage - Cracking of Tail boom Fitting
CF-2009-41R1	2016-11-02	BELL HELICOPTER TEXTRON CANADA (BHTC)	206	Windows - Cockpit Doors and Cabin Emergency Exit Windows / Seals and Wedges - Replacement
2016-0216	2016-10-26	LEONARDO S.p.A. HELICOPTERS	AW189	Fuel - FUEL TRON Flowmeter - Removal
2016-0109R1	2016-10-27	AIRBUS HELICOPTERS	A3 355	Engine - High Pressure Turbine Blades - Inspection / Replacement
2016-0215	2016-10-27	ROLLS-ROYCE PLC	TRENT 1000	
2016-2014	2016-10-27	© IHS CORP	TC7	



**Keyword:**  [Search](#)

[advanced search](#)

**IMPORTANT NOTICE**  
**AD WORKSHOP (UPDATE!)**

The 4th European Aviation Safety Agency (EASA) Airworthiness Directives (AD) Workshop will be on 06-07 November 2016 in Cologne.

The draft agenda is available here. More information and online registration are available here. EASA Safety Information Section

**List of Mandatory Continuing Airworthiness Information**  
 Displaying records 41 to 60 out of a total of 12265 publications.

Number	Issued by	Issue date	Subject	Approval holder / Type Designation	Effective date	Attachment
2016-0224		2016-11-09	Landing Gear – Main Landing Gear – Inspection / Replacement	BAE SYSTEMS (OPERATIONS) LTD HP 137 JETSTREAM MK.1 JETSTREAM200 JETSTREAM300	2016-11-23	250 kb 165 kb
2016-0225		2016-11-09	Wings – Rear Spar Root Joint Attachment Fittings at Wing Rib 2 – Inspection	BAE SYSTEMS (OPERATIONS) LTD APPRO:46R2 BAE146	2016-11-23	382 kb 208 kb
2016-0223		2016-11-08	Engine – High Pressure Compressor Stage 1-4 Rotor Disc Shafts – Life Limit Reduction	ROLLS-ROYCE PLC RR211 TREAT 800	2016-11-22	356 kb 955 kb
US-2016-19-12		2016-11-07	Fuel - Wire Bundles of the Front Spars and Rear Spars of the Wings - Installation / Inspection	BOEING 747	2016-11-14	98 kb
16-156		2016-11-07	Door – Auxiliary Wing Landing Gear Door – Inspection serial comment	ARBUS A380		307 kb
16-155		2016-11-07	Power Plant – CFM56 Engines Fan Cowl Door Latch with Key and Flag – Modification serial comment	ARBUS A318 A320 A321		372 kb
US-2016-22-02		2016-11-07	Fuelage - Skin Lap Splice - Inspection	ERBUS E-175	2016-12-09	21 kb
2016-0222		2016-11-07	Wings – Bottom Panel 2 at Rib 2 Interfaces – Inspection	ARBUS A318 A320 A321	2016-11-21	201 kb 998 kb
2016-0221		2016-11-04	Main Rotor – Main Rotor Spindle – Inspection	ENSTROM HELICOPTER CORPORATION 280 F-28	2016-11-18	384 kb 670 kb
2016-0220		2016-11-04	Rotor Flight Controls – Dual Hydraulic System – Modification	ARBUS HELICOPTERS AS 350 / EC 130	2016-11-18	342 kb 625 kb
US-2016-18-16		2016-11-03	Centre/Auxiliary Tank Fuel Boost Pumps Installation - Modifications / FS 2 Fuel System	BOEING	2016-10-31	362 kb



[←](#) [→](#) [↶](#) [↷](#) [⌂](#) [✱](#) [✱](#) [✱](#)

[http://easa.europa.eu/lib/doc/page-1](#) [EASA Safety Publications Tool](#) [Akav](#) [Redigera](#) [Visa](#) [Favoriter](#) [Verktyg](#) [Hjelp](#)

**EASA** You are not logged in  
 European Aviation Safety Agency

[NCAI](#) [SIB](#) [CZIB](#) [Advanced search](#) [Export list as...](#) [User guide](#) [Related information](#) [AD Biweekly reports](#) [Register](#) [Login](#)

## Safety Publications Tool

**List of Safety Information**  
 Displaying records 1 to 20 out of a total of 663 publications.

Number	Issued by	Issued date	Subject	Approval history / Effective date	Attachment
2016-18	EU	2016-11-28	[B] Dynamic Rollout during Hoisting and/or External Sling Load Operations	[B] Safety Information Bulletin - Operations - Airworthiness	327.Lb
CASR-2016-11	CA	2016-11-27	[B] Bell Helicopter Textron Canada 206L Helicopters - Inspection and Certification of Engine Mount Legs	[B] Safety Information Bulletin - Airworthiness	83.Lb
2016-27	EU	2016-11-17	[B] Learjet 35, Models 60 Aeroplanes - Inspection of Upper Fuelage Skin under the Aft Oxygen Line Fitting	[B] Safety Information Bulletin - Airworthiness	329.Lb
EE-16-27	EE	2016-11-03	[B] Air Tractor AT-250, AT-300, AT-400, AT-500, AT-600 and AT-600 Series Aeroplanes - Wing Trailing Edge Flap Control System	[B] Safety Information Bulletin - Airworthiness	36.Lb
SACU-6012	US	2016-10-27	[B] Brexite Battery, Inc. - Lithium Ion Battery Shipments	[B] Safety Information Bulletin - Operations	133.Lb
2016-16	EU	2016-10-14	[B] ANSAFE Restraint Systems - Jammed Cockpit Seat Belt Buckles	[B] Safety Information Bulletin - Airworthiness	351.Lb
2016-1481	EU	2016-10-13	[B] [Correction] Safety precautions regarding the transport by air of damaged, defective or recalled lithium batteries	[B] Safety Information Bulletin - Operations	359.Lb
2016-15	EU	2016-09-30	[B] Improperly Crimped Spark Plugs	[B] Safety Information Bulletin - Airworthiness	320.Lb
NM-16-24	US	2016-09-19	[B] Learjet 25, 28, 29, 31, 35, 36, and 35 Fuelage Main Plate/Skin	[B] Safety Information Bulletin - Airworthiness	50.Lb
LPN2016-20160519004	US	2016-09-15	[B] Air-Safe Restraint Systems, Sub-Assemblies and Articles sold without Production Approval	[B] Safety Information Bulletin - Airworthiness	64.Lb 792.Lb
LPN2016-20160212004	US	2016-09-15	[B] CAE manufactured and sold parts without FAA production approval	[B] Safety Information Bulletin - Airworthiness	85.Lb
2016-13	EU	2016-09-09	[B] WITHDRAWN - REPLACED BY EASA SID 2016-14	[B] Safety Information Bulletin - Operations	78.Lb
2016-12	EU	2016-09-08	[B] Notification of Suspected Unapproved Propellers	[B] Safety Information Bulletin - Airworthiness	324.Lb
NE-16-22	US	2016-09-05	[B] Pratt & Whitney 7150-200 series engines - Turbine Engine Combustion Section	[B] Safety Information Bulletin - Airworthiness	42.Lb