

Maritime Department

Designation TSS 2009-1587

Date 2009-10-22

Document type

NOTICE FROM

SHIP TRAFFIC SECTION

No. 05/2009 (summary)

Administrative officer

Monica Sundklev

Page 1(5)

This is only a summary in English. For the complete text, see the Swedish version.

# Recommendation regarding general call outside established VTS areas

The Swedish Transport Agency recommends

- vessels with a gross tonnage of 300 or more or vessels with a length of 45 metres or more, *or*
- towing vessels with a total length of 45 metres or more including the tow,

to participate in the general call reporting outside VTS areas. Masters on other vessels, equipped with VHF radio, should maintain a continuous listening watch on the dedicated VHF channel. Such a vessel should make a general call if suitable according to the circumstances.

The master or the officer in charge of the navigational watch should:

- 1. <u>listen</u> to the dedicated VHF channel well in advance before leaving quay or anchorage in close vicinity of the fairway and during the whole passage; and
- 2. <u>make a general call</u> immediately before leaving a quay or before leaving an anchorage *and* when passing the reporting points according to the annex, stating the following information in English:
  - 1. General call (All ships) and the VHF channel in question;
  - 2. Vessel's type and name;
  - 3. Name and geographical position of the reporting point or place of departure;
  - 4. Intended route; and
  - 5. Destination.

The passage time may be given when passage is not made in immediate connection to the reporting.

Example of a general call in Kalmarsund: "All ships on channel 16. Tanker URBAN passing reporting point no 2 at Sillåsen, southbound for Kalmar."

Designation TSS 2009-1587 Document type **NOTICE FROM** SHIP TRAFFIC SECTION No. 05/2009 (summary)

Page 2(5)

Maritime Department

Date 2009-10-22

Administrative officer Monica Sundklev

Annex

## **Bay of Bothnia Maritime Traffic Area**

| Reporting name     | Geographical location and position | VHF<br>channel | To harbour/area<br>(direction) |
|--------------------|------------------------------------|----------------|--------------------------------|
| Reporting point 7  | Malören (65°32N 23°25E)            | 16             | Axelsvik, Karlsborg, Töre      |
| Reporting point 8  | Nygrån (65°01N 21°46E)             | 16             | Piteå                          |
| Reporting point 9  | Gåsören (64°40N 21°30E)            | 16             | Skelleftehamn                  |
| Reporting point 10 | Väktaren (63°33N 20°30E)           | 16             | Umeå, Holmsund                 |
| Reporting point 12 | Storbådan (63°21N 19°35E)          | 16             | Rundvik                        |
| Reporting point 13 | Vallinsgrund (63°18N 19°20E)       | 16             | Husum                          |
| Reporting point 14 | Skaghällan (63°10N 19°00E)         | 16             | Örnsköldsvik                   |
| Reporting point 15 | Trysunda (63°10N 18°48E)           | 16             | Köpmanholmen                   |

A general call is also recommended immediately before leaving the quay of above mentioned harbours or before leaving an anchorage in close vicinity of the fairway to the harbours.

### **Sea of Bothnia Maritime Traffic Area**

| Reporting name                  | Geographical location and position   | VHF<br>channel | To harbour/area (direction)              |
|---------------------------------|--------------------------------------|----------------|--|
| Reporting point 65              | Brunne (62°56,0N 17°50,5E)           | 16             | Southbound to the sea                    |
| Reporting point 64              | Ramön (62°50,0N 17°54,0E)            | 16             | Kramfors, Bollstabruk                    |
| Reporting point 63              | Storön nord (62°47,6N 18°17,0E)      | 16             | Kramfors, Bollstabruk,                   |
| Reporting point 62              | Storön syd (62°43,4N 18°12,8E)       | 16             | Gustavsvik, Lugnvik,<br>Väja             |
| Reporting point 61              | Härnö (62°36,6N 18°05,8E)            | 16             | Härnösand and passing Sannasundet        |
| Reporting point 53              | Åstholmsudde (62°22,8N 17°43,8E)     | 16             | Sundsvall, Stockvik,                     |
| Reporting point 52              | Brämön nord (62°17,4N 17°40,4E)      | 16             | Tunadal, Söråker,<br>Östrand, Vivstavarv |
| Reporting point 41 <sup>1</sup> | Britas klack (61°53,1N 17°27,7E)     | <del>16</del>  | <del>Stocka</del>                        |
| Reporting point 32              | Hudikgrund (61°35,0N 17°24,0E)       | 16             | Hudiksvall, Skärnäs                      |
| Reporting point 31              | Tihällsten (61°31,5N 17°19,0E)       | 16             |  |
| Reporting point 23              | Hällgrund (61°15,8N 17°22,0E)        | 16             | Söderhamn, Sandarne                      |
| Reporting point 22              | Blomman (61°11,5N 17°17,5E)          | 16             | Vallvik, Ljusne                          |
| Reporting point 21              | Storjungfrun syd (61°07,3N 17°20,0E) | 16             |  |
| Reporting point 13              | Välkommen (60°57,8N 17°15,0E)        | 16             | Norrsundet                               |
| Reporting point 12              | Purrutsgrund (60°46,7N 17°27,5E      | 16             | Gävle, Karskär,                          |
| Reporting point 11              | Eggegrund (60°42,7N 17°33,0E)        | 16             | Granudden,<br>Fredrikskans, Skutskär     |

<sup>&</sup>lt;sup>1</sup> Withdrawn 22 August 2012, see Ufs (NtM) 2012:414/8091



Maritime Department

Designation TSS 2009-1587

Date 2009-10-22 Document type

**NOTICE FROM SHIP TRAFFIC SECTION** No. 05/2009 (summary)

Administrative officer Monica Sundklev

A general call is also recommended immediately before leaving the quay of above mentioned harbours or before leaving an anchorage in close vicinity of the fairway to the harbours.

Page

3(5)



Designation TSS 2009-1587

NOTICE FROM SHIP TRAFFIC SECTION No. 05/2009 (summary) Page 4(5)

Maritime Department

Date 2009-10-22

Administrative officer

Monica Sundkley

Document type

Annex (cont.)

#### **East Coast Maritime Traffic Area**

| Reporting name       | Geographical location and position | VHF<br>channel | To harbour/area<br>(direction)                              |
|----------------------|------------------------------------|----------------|---|
| Reporting point 14   | Simpnäsklubb (59°53,9'N 19°04,9'E) | 73             | Norrtälje, Stockholm archipelago (southbound)               |
| Reporting point 14b  | Tjockö (59°45,5'N 19°05,9'E)       | 73             | Norrtälje, Arholma, Simpnäs (northeast- and northwestbound) |
| Reporting point 51 * | Visby (57°38,0'N 18°16,1'E)        | 16             | Visby (northeastbound)                                      |

<sup>\*</sup> Reporting should be made 15 minutes before passing the reporting point during May-September.

A general call is also recommended immediately before leaving the quay of above mentioned harbours or before leaving an anchorage in close vicinity of the fairway to the harbours.

#### **South Coast Maritime Traffic Area**

| Reporting name     | Geographical location and position        | VHF<br>channel | To harbour/area<br>(direction)                   |
|--------------------|---|----------------|--|
| Reporting point 5  | Västervik entrance (57°44,9'N 16°49,1'E)  | 16             | Västervik<br>(westbound)                         |
| Reporting point 4  | North Furö (57°17,6'N 16°37,3'E)          | 16             | Oskarshamn<br>(southwestbound)                   |
| Reporting point 3* | South Furö (57°15,7'N 16°37,3'E)          | 16             | Oskarshamn<br>(northwestbound)                   |
| Reporting point 2  | Sillåsen (56°47,0'N 16°30,5'E)            | 16             | Kalmar/Kalmarsund (southbound)                   |
| Reporting point 1  | Hagbygrundet (56°32,0'N 16°18,0'E)        | 16             | Kalmar/Kalmarsund (northbound)                   |
| Reporting point 7  | Karlskrona angöring (56°03,2'N 15°33,4'E) | 16             | Karlskrona<br>(northbound)                       |
| Reporting point 8  | Karlshamn East (56°07,2'N 14°53,4'E)      | 16             | Karlshamn, Stärnö vindhamn (northbound)          |
| Reporting point 9  | Karlshamn West (56°06,9'N 14°49,0'E)      | 16             | Stilleryd, Kölö, Elleholm (north- and westbound) |

<sup>\*</sup> Reporting should be made 15 minutes before passing the reporting point.

A general call is also recommended immediately before leaving the quay of above mentioned harbours or before leaving an anchorage in close vicinity of the fairway to the harbours.



Designation TSS 2009-1587

NOTICE FROM SHIP TRAFFIC SECTION No. 05/2009 (summary) Page 5(5)

Maritime Department

Date 2009-10-22

Administrative officer

Monica Sundklev

Document type

Annex (cont.)

#### **West Coast Maritime Traffic Area**

| Reporting name      | Geographical location and position                       | VHF<br>channel | To harbour/area<br>(direction) |
|---------------------|--|----------------|--------------------------------|
| Reporting point 43* | Halmstad entrance (56°36,5'N 12°47,0'E)                  | 16             | Halmstad<br>(northeastbound)   |
| Reporting point 42* | Falkenberg entrance (56°51,1'N 12°26,1'E)                | 16             | Falkenberg (northbound)        |
| Reporting point 41* | Varberg entrance (57°05,0'N 12°13,0'E)                   | 16             | Varberg<br>(northbound)        |
| Reporting point 21  | Strömstad entrance (via Bulthålan) (58°56,3'N 11°03,9'E) | 16             | Strömstad<br>(eastbound)       |

<sup>\*</sup> Pre-notice should also be made 20 minutes before passing the reporting point.

A general call is also recommended immediately before leaving the quay of above mentioned harbours or before leaving an anchorage in close vicinity of the fairway to the harbours.

#### Lake Vänern Maritime Traffic Area

Regarding general calls at Lake Vänern special regulations apply.